ABSTRACT

A method of connecting an electronic part, containing: forming an electroless nickel plating coat containing phosphorous on a substrate metal layer which constitutes a connecting terminal of an electronic part; and carrying out connecting to the nickel plating coat through a lead-free solder, wherein a half-width of X-ray diffraction of a (111) plane of Ni crystal in the nickel plating coat is 5 degrees or less.

5

10